

Alkaline Cleaner for Condensers



Product Description

Alkaline Ultra is an active substances formula that, diluted with water, creates an ultimate powerful alkaline cleaner for condenser which can effectively degreases surfaces by removing even the most stubborn deposits of organic residues, grease, dust, pollen and smog, restoring the efficiency of the condenser heat exchange.

The optimal recommended dilution is 50 mL per liter of water. The supplied dispenser allows to obtain the desired quantity of cleaner with the precision that a so performing chemical product needs, without dilute the whole product in a single solution.

The extraordinary formula of these active substances allows to overcome the limits of water hardness. In fact, this product can be diluted with any type of water, including very hard ones and fo not leave any residue on the surfaces. It is the best solution to remove organic residues with a deep cleansing action.

Features

- For condensers
- Concentrated, dilution 1:20
- Alkaline cleaner

- Remove organic residues and grease.
- Easy to dose.

Condensers Application


- 1. Shake the glass bottle to obitain a homogeneus solution.
- 2. Dilute the product 1:20 in a container with the right quantity of water (water first) and shake.
- 3. Turn off the system.
- **4.** Apply the product on the surface to treat.
- 5. Wait for 5 minutes to allow the cleaner to performe.
- 6. Rinse with plenty of water.
- 7. If needed, dry with soft cloth.











When used together with an acid cleaner in case of particularly compromised condenser, use Alkaline Ultra as second step.

Packaging available



Alkaline Ultra 250 ml glass bottle in carton box Counter display with 24 pcs

ArtNr.	8	**
AB1223.Q.S1	24	-



Carton box and counter display made of recycled paper.

Danger Indications



Hazard statements: H315 Causes skin irritation. H318 Causes serious eye damage.

Precautionary statements: P280 Wear protective gloves/protective clothing/eye protection/face protection. P302+P352 IF ON SKIN: Wash with plenty of water. P305+P351+P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing

Contains: ethoxylated fatty alcohols, sodium hydroxide, tetrasodium ethylene diamine tetraacetate

Professional usage product: wear the appropriate protective uniform. Read the instructions on the label carefully.

